

PROCESS SPECIFICATION

PROCESS SPECIFICATION NUMBER: ERA-1021
412 Auxiliary Fuel Tanks
CLOSURE PROCEDURE FOR THE PRIMARY SHELL

PREPARED BY:

DATE: 6/12/87

John E. Stanley MESH PLASTICS LTD.

APPROVALS

THE BOY WINE THAT THAT THAT BOYS BOYS BOYS BOYS BOYS WAS DOOR THAT THAT BOYS BOYS BOYS BOYS BOYS BOYS BOYS BOYS	And the man per man days and they may the man per man and the man		l
MANUFACTURING	QUALITY CONTROL	ENGINEERING	
Berul 20 Eleken	John E Its	Sund! E-	MESH
Rolet Hanne	Savil & Mark	Landly	ERA
	7		



PROCESS SPECIFICATION

Scope: This specification outlines the requirements

for the closure procedure for the primary shell

of the 412 Auxiliary Fuel Tanks.

Conformation: This specification does not conform to any

existing government specification.

Subcontractors: MESH PLASTICS, LTD. of Lake Charles, Louisiana,

or its subcontractor shall be the only subcontractors qualified to construct the FRP requirements and shall comply with this process specification. Any deviations or variations are to be submitted to ERA for approval with proper documentation prior to

fabrication.

Conflicts: In the event of a conflict with engineering

drawing(s) and this specification, the

drawing(s) shall govern.

Closure procedure for the Primary Shell

of the 412 Auxiliary Fuel Tanks

Rev.	Date	Pages		Appi cturing ERA	ovals Quality MESH	Control ERA	Engine	ering ERA_
ΙŖ	6/12/87	ALL	Hul)	SH	121	Un.	1882	#
The second secon	ere litaka	Language and Agency of Administration of Agency and Balling and Ba	Makalagaga, Malana, Malana, Makanati (Malanati Malanati Malanati Malanati Malanati Malanati Malanati Malanati M	. <u>————————————————————————————————————</u>	erende van deusgen Herman de deus von de para tribuser van deus von deus verbeiligen van deus verbeiligen. Ver		A SANTANA AND AND AND AND AND AND AND AND AND	
Maryon Makes	aran jegun di ta'u' i ilikin gel dagan - kilapan - dikala ini di talah ini di urun beri	Martine de la proposition della proposition dell	A varience, even months on historic blance Adequa Adequa Benno Benno n	Adding the Control of	The section of the se		- www.prior-Macronn Macrons, Annouse Marques Alburgs, or Mil	
	August von state und state en			water to the state of the state				Para Paul de Mandalo Mandalo, mar de Para Paul de Mandalo, de la composició de Mandalo, de la composició de Mandalo, de la composició de la co
dynamical parameter adapter regions you believe to delib	and the state of t					To the state of th		

PAGE 1 of 14

ERA PS _____1021

REV__IR_

DATE ____6/12/87

MATERIALS

MATERIAL MANUFACTURER NAME Derakane 470-36 Dow Chemical Resin Midland, MI Promoter Cobalt Napthenate AKZO Chemie New Brunswick, NJ Accelerator Dimethylaniline Buffalo Colors West Paterson, NJ MEKP Catalyst Hi Point 90 Witco Chemical Richmond, CA Lupersol DHD 9 Lucidol Chemical Buffalo, NY UV Inhibitor . UV-9 Industrial Chemicals Atlanta, GA

PAGE 2 of 14

	DATE 6/26/95	ENGINEER	RING ORE	DER	E.O. No. A − 1	SHT. OF
7	BY - Harville	PROCESS	specific,	ATION	ENTERED ON	
RE/		ADD ALT P/N FO GLASS MAT (M12		1/2 0		
3/	/4 oz TYPE "e	Z" GLASS MAT.	M113-3/4 OR M127-3/4	w oz CE	ichita fa	LLS, TX. D
**************************************	1/2 oz TYPE	"E" GLASS MAT.		1/2 02	z CERTA ICHITA FA z CERTA ICHITA FA	INTEED

ERA PS 1021 REV IR DATE 6/12/87

MATERIALS

MANUFACTURER NAME MATERIAL Dequssa Corp. Aerosil Putty filler Teterboro, NJ (Amorphous Fumed Silica) Cabot Corp. Cabosil Boston, MA Owens-Corning 731 ED Milled Fibers Anderson, S.C. 1-1/2 oz Type 'E' glass mat Compatamat - 1-1/2 oz. PPG Industries Shelby, NC Certainteed $M113 - 1 - 1/2 \circ 2.$ Wichita Falls, TX Modiglass Reichold Chemical 10 mil 'C' glass, or Bremen, OH Manville Corp. Manville Glass Denver, CO

10 mil 'A' glass veil Surglass

Superior Glass Bremen, OH ERA PS 1021 REV IR DATE 6/12/87

MATERIALS ·

MANUFACTURER MATERIAL NAME

Industrial Chemicals TF-100 Paraffinated Styrene Atlanta, GA

36 Grit Type D 60 Grit Type C 80 Grit Type C 3M Corp. Grinding Discs St. Paul, MN

						The second secon
ERA	PS	1021	REV_	IR	DATE	6/12/87

Laminate Manufacture

- 1) Fit piece #41228-202-040-001/002(left/right) in opening on piece #41228-202-041-001/002(left/right) and check to see that a gap of 0.06" to 0.12" is obtained between the two pieces. Separate the two pieces and seal the exposed edges as follows.
- 2) Apply one layer of 10 mil veil to all cut edges. Saturate with 470-36 resin containing UV inhibitor (no pigment). Deaerate with serrated rollers. Allow to cure.
- 3) Dress down any areas of roughness and apply a hot wax coat of 470-36 resin containing UV inhibitor and Paraffinated styrene solution. Allow to cure until tack free.
- 4) Lightly sand the wax surface to allow bonding using 80 grit sandpaper.
- 5) Grind recessed areas on pieces #41228-202-040-001/002(left/right) and #41228-202-041-001/002(left/right) where bonding will occur using 36 grit grinding discs.
- 6) Using a vacuum, clean the inside of the tank shell after all parts have been installed, excluding the shell closure piece.
- 7) Wipe the entire interior surface out carefully with a tack rag.
- 8) Wipe the inner surface of the closure piece with a tack rag. Blank off all openings in the shell and closure.
- 9) Fit the pieces together using temporary closure clips. Fill gaps between the clips with putty. Allow to cure until putty hardens.
- 10) Remove all temporary closure clips by pushing them into the tank & removing through the access openings.
- 11) Fill areas where clips were located with putty. Allow to cure. Smooth any rough areas with 36 grit grinding discs.
- 12) Apply 1" wide strip of 10 mil veil over putty joint. Saturate with Derakane 470-36 containing UV inhibitor (no pigment). Deaerate with serrated rollers.
- 13) Apply 2" wide strip of 1-1/2 oz type E glass mat. Saturate with Derakane 470-36 containing UV inhibitor (no pigment). Deaerate with serrated rollers.

ERA	PS	1021	REV	IR	DATE	6/12/87
Max 19 // W			accompanies de la constante de			ACCUPATION OF THE PARTY OF THE

LAMINATE MANUFACTURE

- 14) Apply 3" wide strip of 1-1/2 oz type E glass mat. Saturate with Derakane 470-36 containing UV inhibitor (no pigment). Deaerate with serrated rollers.
- 15) Apply 4" wide strip of 1-1/2 oz type E glass mat. Saturate with Derakane 470-36 containing UV inhibitor (no pigment). Deaerate with serrated rollers.
- 16) Apply second 4" wide strip of 1-1/2 oz type E glass mat. Saturate with Derakane 470-36 containing UV inhibitor (no pigment). Deaerate with serrated rollers.
- 17) Apply third 4" wide strip of 1-1/2 oz type E glass mat. Saturate with Derakane 470-36 containing UV inhibitor (no pigment). Deaerate with serrated rollers.
- 18) Apply fourth 4" wide strip of 1-1/2 oz type E glass mat. Saturate with Derakane 470-36 containing UV inhibitor (no pigment). Deaerate with serrated rollers.
- 19) Sand lay-up to the contour of the tank using 36 grit sanding discs.
- 20) Inspect for any low spots in lay up an fill in as required.

Page 6 of 14

ERA	PS	1021	REV_	IR	DATE	6/12/87
-----	----	------	------	----	------	---------

INSPECTION

It is the purpose of the inspection to verify that each part has been fabricated in accordance with and meets the requirements of this specification.

RESPONSIBILITIES: It is the responsibility of the fabricator to make

available to ERA Helicopter or his authorized representative any or all of the following:

Records: Records pertaining to the part(s) being purchased

shall be supplied when requested. These may include:

Materials specifications

Equipment drawings or mold jig

Materials test results.

Dimensional verification reports.

Rework and repair reports.

MATERIALS:

Raw materials used for laminates shall be virgin materials and shall be free of contaminants as described on pgs. 11, 12, 13, and 14.

FABRICATED PARTS:

The part to be inspected shall be properly located and positioned, and shall be in condition to permit safe and thorough inspection. Reasonable means shall be provided to permit the inspector to visually examine the entire inner and outer surfaces of the part.

Allowable defects are listed on pgs. 9 and 10.

The following inspection tools and equipment shall be made available for use by the inspector.

Barcol hardness tester.
Acetone squeeze bottle with acetone.
Extension cord with ground fault switch.
A vapor tight inspection light.
Thickness gauge.

PAGE 7 of 14

ERA	PS	1021	REV_	IR	D A	TE	6/12/87
-----	----	------	------	----	-----	----	---------

INSPECTION

TEST OF FINISHED PARTS:

The following basic tests shall be included as a minimum in the Acceptance Inspection.

Barcol Hardness Test - A test of resin cure shall be made in accordance with ASTM D2583. Take 10 readings, discard highest and lowest, average the remaining readings. Minimum acceptable average reading is 30.

Surface Cure Test - An acetone test shall be used to detect surface inhibition on surfaces exposed to air during cure. The procedure that shall be used is the following: rub a few drops of acetone on the surface and check for tackiness after the acetone has evaporated. Persistent tackiness indicates incomplete cure.

Dimensions - The inspector shall be provided with copies of all approved drawings or mold jigs.

OTHER APPLICABLE DOCUMENTS:

ASTM Standards

- C 581-74-Test Method for Chemical Resistance of Thermosetting Resins Used in Glass Fiber Reinforced Structures.
- D 638-77a-Test method for Tensile Properties of Plastics.
- D 790-71-Test Methods for Flexural Properties of Plastics and Electrical Insulating Materials.
- D 883-78a-Definitions of Terms Relating to Plastics.
- D 2583-75-Test Method for Identation Hardness of Rigid Plastics by Means of a Barcol Impressor.

PAGE 8 of 14

ERA	P S	1021	REV_	IR	DA.	TE	6/12/87

ALLOWABLE DEFECTS Surface inspected Defect None Cracks(through part) Max dimension 1/2 in., max Crazing density 5 per sq. ft. min 2 (fine surface cracks) in apart Blisters(rounded Max 1/4 in., dia x 1/8 in. elevations of the high, max 1 per sq ft, min laminate surface over 2 in apart bubbles) Max deviation, 20% of wall Wrinkles and solid thickness but not exceeding blisters 1/8 in. Max dimensions, 1/8 in dia Pits(craters in the x 1/16 in deep, max density laminate surface) 10 per sq. ft. Max dimensions, 1/16 in dia. Surface porosity(pinx 1/16 in deep, max density holes or pores in the 10 per sq. ft. laminate) Max dimension of break, 1/4 Chips in, and thickness no greater than 20 percent of wall thickness, max density 1 per sq ft Max dimension, 2 sq in. per Dry spot(nonwetted sq ft reinforcing) 1/8 in. max dia, 4 per sq Entrapped air (bubbles in. max density; 1/16 in. or voids in the max dia. 10 per sq in. max laminate) density

PAGE 9 of 14

ERA PS 1021 REV IR DATE 6/12/87

ALLOWABLE DEFECTS

Defect
Exposed Glass
None
Burned Areas
None
Exposure of cut edges
None
Scratches
Max length 1 in. max depth 0.010 in.
Foreign Matter

1/16 in.dia, max density 1 per sq ft

PAGE 10 of 14

ERA	P S	1021	REV_	IR	D	Α.	TE	6/12/87
-----	-----	------	------	----	---	----	----	---------

FIBERGLASS SURFACING MAT

1.0 Scope

1.1 The scope of these procedures is to describe the visual, physical and mechanical parameters which characterize fiberglass surfacing mat used by the fabricator.

2.0 Definitions

- 2.1 Fiberglass Surfacing Mat A random arrangement of glass fibers bonded with a binder to form a thin porous mat which is supplied in roll form. Surfacing mat is usually used to reinforce the corrosion resistant resin rich liner on the inside of equipment and to provide a smooth surface on the exterior of equipment.
- 2.2 Binder Chemical treatment applied to the jackstraw arrangement of glass fibers to give the mat integrity. Specific binders are utilized to promote chemical compatibility with the various laminating resins used.
- 2.3 Slugs Unfiberized beads of glass.
- 3.0 Requirements
- 3.1 Visual Requirements Each roll of fiberglass surfacing mat shall be inspected to insure it is consistent in color, texture and appearance. Any holes, cuts or visual irregularities shall be removed from the mat prior to or during fabrication.
- 3.1.1 Slugs Mat which contains more than four slugs per 100 lineal feet is rejectable.
- 3.1.2 Wrinkles Crosswise wrinkles or waves that are visible at a 45 deg. angle and lengthwise wrinkles that can be readily flattened under pressure and that do not crease or change the dimensions of the mat are acceptable.
- 3.1.3 Wet Spots and Bar Marks The mat shall be free from these defects.
- 3.1.4 Delamination The mat shall not delaminate, i.e. shall not separate into layers in coming off the roll.

PAGE 11 of 14

ERA PROCESS SPECIFICATION

ERA	PS	1021	REV_	IR	DATE.	6/12/87
-----	----	------	------	----	-------	---------

FIBERGLASS SURFACING MAT

- 3.2 Physical Properties
- 3.2.1 Thickness The thickness of the mat in each roll shall be measured.
- 3.3 Packaging Requirement Packaging shall be visually inspected to assure proper labeling and that the package is free from damage that may render the mat unusable.
- 3.3.1 The mat shall be packaged in an unbroken carton as shipped from the mat manufacturer's factory. The mat used shall not be repackaged in the distribution of the mat after the manufacturer has shipped the mat.
- 3.4 Documentation It is the responsibility of the fabricator to maintain records showing the results of all material testing. This information shall show at a minimum, the following:
- (a) Form of material
- (b) Manufacturer
- (c) Manufacturer's product description including binder type (treatment)
- (d) Manufacturer's product code
- (e) Production date, if available, or production code on carton.
- (f) Property measured and value recorded
 - * Visual inspection
 - * Width
 - * Thickness
 - * Packaging
- (g) Job number (Internal Fabricator Control Number)
- (h) Fabricated part identification number

PAGE 12 of 14

ERA	PS	1021	REV_	IR	DATE_	6/12/87
-----	----	------	------	----	-------	---------

FIBERGLASS CHOPPED STRAND MAT

1.0 Scope

1.1 The scope of these procedures is to describe the visual, physical and mechanical parameters which characterize fiberglass chopped strand mat used by the fabricator.

2.0 Definitions

2.1 Chopped Strand Mat - Chopped strand mat is made from randomly oriented glass strands which are held together in mat form using a binder. Each strand contains a sizing.

3.0 Requirements

- 3.1 Visual Requirements Each roll of chopped strand mat shall be inspected to insure it is consistent in color, texture and appearance. It shall be free from surface irregularities, fluffy masses, dirt spots or other foreign material; water spots, knots, binder spots larger than 2" in diameter, clumps of strands and tears of holes which may result form removal of defects.
- 3.2 Physical Requirements
- 3.2.1 Weight The square foot weight of the mat shall be measured for each carton of mat used. All specimens shall fall within the range specified for the product.
- 3.3 Packaging Requirement Packaging shall be visually inspected to assure proper labeling and that the package is free from damage that may render the mat unusable.
- 3.3.1 The mat shall be packaged in an unbroken carton as shipped from the mat manufacturer's factory. The mat used shall not be repackaged in the distribution of the mat after the manufacturer has shipped the mat.

PAGE 13 of 14

ERA	рs	1021	R E V	IR	DATE_	6/12/87
Dec			#Macroscopic 2005	فالأنطاقية الإكامالية البيالة فيستجمع يبيها يوري	As an amount of the Contract o	

FIBERGLASS CHOPPED STRAND MAT

- 3.4 Documentation It is the responsibility of the fabricator to maintain records showing the results of all material testing. This information shall show at a minimum, the following:
- (a) Form of material
- (b) Manufacturer
- (c) Manufacturer's product description including binder type (treatment)
- (d) Manufacturer's product code
- (e) Production date, if available, or production code on carton.
- (f) Property measured and value recorded
 - * Visual inspection
 - * Width
 - * Thickness
 - * Packaging
- (g) Job number (Internal Fabricator Control Number)
- (h) Fabricated part identification number

PAGE 14 of 14